
FES Commissioning Tasks
Rev1 - RK: 020326
3/25-3/29
4/1-4/5
4/8-4/12
4/15-4/19
4/22-4/26
4/29-5/3
5/6-5/10
5/13-5/17
5/20-5/24
5/27-5/31
Individual system checkout
Creating procedures
Integrated systems checkout
First beam
Diagnostics calibration with beam
Physics commissioning A
Phys. commiss. B (semi-autom.)
Chopping tests
Special event
High duty-factor operation
Endurance test
Full specifications