1000 Amp Clamp Meters

- 1000A current capability
- Large digit display
- Audible continuity
- Diode test
- Data hold
- Auto power-off
- Low battery indicator
- Overload protection on all ranges
- Lifetime limited warranty
- CAT III – 600V

Includes carrying case

Description	Cat. No.
1000AAC Clamp Meter, standard model	**61-720**
1000AAC Clamp Meter, True RMS, frequency, peak hold	**61-722**
1000AAC Clamp Meter, True RMS, DC current, frequency, backlit display	**61-724**
1000AAC Clamp Meter, True RMS, DC current, capacitance, frequency, peak hold, high speed analog bar graph	**61-726**

Specifications	61-720		61-722		61-724		61-726	
	Range & Resolution	Accuracy	Range & Resolution	Accuracy	Range & Resolution	Accuracy	Range & Resolution	Accuracy
AC Voltage	200.0/600 V	1.2%	200.0/600 V	1.2%	200.0/600 V	1.2%	4.000/40.00/400.0/600 V Auto	1.7%
DC Voltage	2.000/200.0/600 V	0.5%	600 V	0.5%	600 V	0.5%	400.0m/4.000/40.00/ 400.0/600 V	0.25%
AC Current	20.00/200.0/1000 A	1.5%	20.00/200.0/1000 A	1.5%	200.0/1000 A	1.75%	400.0/1000 A	1.75%
DC Current	—	—	—	—	200.0/1200 A	1.5%	400.0/1200 A	1.5%
Resistance	200.0/200.0k Ω	1.2%	2.000k/200.0k Ω	1.2%	2.000k/200.0k Ω	1.2%	400.0/4.000k/40.00k/400.0k/ 4.000M/40.00M Ω Auto	0.3%
Capacitance	—	—	—	—	—	—	4.000n/40.00n/400.0n/ 4.000μ F Auto	3.0%
Instant Continuity	✔	—	✔	—	✔	—	✔	—
Diode Test	✔	—	✔	—	✔	—	✔	—
Frequency	—	—	20.00/2.000k Hz (Auto)	0.1%	20.00/2.000k Hz Auto	0.1%	100.00/1.0000k/100.00k/ 500.0k Hz Auto	0.1%