




**MBraun UNilab
Glovebox System**



SETUP



HAZARDS



ELECTRICAL HAZARD

This equipment is operated on a high voltage system and may remain charged after being powered off



SUFFOCATION HAZARD

There is a risk of asphyxiation when working with inert gasses.



GENERAL HAZARDS

Depending on the type of work being performed in the box, thermal, mechanical, electrical, and/or chemical hazards may be present.

PREVENTION



EYE PROTECTION

Wear safety glasses while operating.



PROTECTIVE GLOVES

Wear appropriate gloves for heat and chemical usage.



NON-SLIP, CLOSED SHOES

Wear non-slip, closed shoes to avoid spills.



READ MANUAL

Become familiar with this guide before operating.

For additional help contact the Lab Space Manager